

1

2

3

4

5

6

RevNo	Revision note	Date	Signature	Checked

Section A-A

36°

72.5

36°

A

A

Detail A

5

4

Full Penetration Stainless Weld
Note: Ensure height of weld is below level of back face

Detail B

1.5

Weld saddle to spine full penetration stainless weld 2 places for 30degree arc.

NOTE:
USE JIG TO POSITION BRACKET IN BASE.
ENSURE BRACKET IS EMBEDDED 4MM INTO BASE.
ENSURE BRACKET IS POSITIONED AT 36 DEGREES AS SHOWN.
WELD RIGHT ROUND.
USE JIG TO POSITION SADDLE TO SPINE.
ENSURE SPINE IS EMBEDDED 1.5MM INTO SADDLE.
ENSURE SIDE OF SADDLE IS PARALLEL WITH BASE.
WELD 2 PLACES FOR 30 DEGREE ARC OPPOSITE SIDES.

P. M. INNOVATIONS LTD

This design and representation by way of drawing is the Copyright of P. M. Innovations Ltd and may not be reproduced, copied, transmitted to a third party, or otherwise made use of except by permission of P. M. Innovations Ltd.

CUSTOMER MILES NELSON MANUFACTURING

PROJECT 621 STAINLESS BANISTER BRACKET

Date

17/11/11

Drawn By

P McKinney

Scale
1 : 1

Sheet
1 of 1

1

2

3

4

5

6